



No subject

7:12 PM




▸  1 attachment Preview Open in browser Download



Life is good.



Porch at time of purchase
Left side under block crumbling
4 front posts rotting
Railing missing









Replaced rotten pressure treated steps
with heritage stone to enhance heritage look
that was being lost over time.



Moved steps from middle of porch
to right side for easier access.
Height of porch to ground on right side
less than 2'

